


# SPAZZOLE PER DINAMO TACHIMETRICHE

## SPEEDOMETER DYNAMO BRUSHES




EGO = elettrografite / *electrographite*  
 SM3 - AGB4 = argento-grafite / *silver-graphite*  
 CM3H - CM9 - M70 - CM5H =  
 metalgrafite / *metalgraphite*

Articolo Art.	Dimensioni Dimensions	Qualita' Model	Figura Figure
4001	4x3x10	EGO	30
4002	4x3x13	EGO	30
4003	4x3x14	AGB4	30
4004	4.1x3.1x10	SM3	30
4005	4.1x3.1x10	EGO	31
4006	4x5x15	SM3	30
4007	4.5x4.5x16/14	EGO	33
4008	4.75x3.15x14.5	SM3	94
4009	5x4x10	SM3	30
4010	5x4x16/14	SM3	33
4011	5x4.3x10	SM3	28
4012	5x6x18/15	SM3	33
4013	6x5x15	EGO	30
4014	9.1x6.1x23/21	CM9	33
4015	10x7x21/18	CM3H	33

# SPAZZOLE PER MOTORI A BASSA TENSIONE

## BRUSHES FOR LOW-VOLTAGE MOTORS



CM3H - M70 - CM5H =  
 metalgrafite / *metalgraphite*

Articolo Art.	Dimensioni Dimensions	Qualita' Model	Figura Figure
4051	∅ 6x22/20	CM3H	95
4052	4x3x15	M70	30
4053	4x4x10	M70	11
4054	5x4x13	M70	30
4055	5x5x16	M70	31
4056	5x6x13	M70	30
4057	8x5x20/18	M70	33
4058	8x6x23/20	CM5H	33
4059	9x6x25/22	M70	33
4060	10x6x25	M70	1